Rectory Renovation: Before and After Photos

Archangel Michael Church and Parish Hall

Front of House (North Side)

West side of House

South/East side of House

East side of House

Rectory Renovation: Before and After Photos

Backyard within fenced in area

Walkway between Garage Door to Front of House

Rectory Renovation: Before and After Photos

Inside of Garage

Door into house hallway and to back yard

Garage Ceiling Before

Garage After (Ceiling Patched/Painted as well as walls

Rectory Renovation: Before and After Photos

Hallway looking at Garage Entrance from Inside of House (New flooring and door to garage)



Hallway looking towards Foyer

New flooring

Rectory Renovation: Before and After Photos

Powder Room off Hallway (Next to garage door)

(Everything new except toilet)

Larger Office off hallway from Garage

Rectory Renovation: Before and After Photos



Larger Office adjacent to Philip's office

New Flooring and lighting

Rectory Renovation: Before and After Photos

Philip's 0ffice adjacent to Larger Office and adjacent to Foyer

New ceiling Fan

Rectory Renovation: Before and After Photos

Foyer: Main Front door of House with Philip's Office to Right





Foyer at entrance to House

Rectory Renovation: Before and After Photos

Living Room, View from Foyer

Floor Refinishing

Living Room Funished, views from Foyer and from Living Room into Foyer

Living Room, looking from Dining Room

(New Window Treatments)

Rectory Renovation: Before and After Photos

Dining Room view from Living Room

New Ceiling Fan, can Lights and window treatments

Rectory Renovation: Before and After Photos



New Can Lights and pendant added





KITCHEN REMODEL

Rectory Renovation: Before and After Photos

2nd Floor Bathroom

New Light Exhaust Fan, Lights

New vanity, sink, mirror and bath hardware installed in first floor powder room

Rectory Renovation: Before and After Photos

New Grab Bars Added

Rectory Renovation: Before and After Photos

Archbishop's Office



Rectory Renovation: Before and After Photos

Archbishop's Vestment Room

S

Rectory Renovation: Before and After Photos

Stairs from Basement to Hallway (New flooring on steps)

Basement

View of Basement (Stairs in background)

Laundry Area (to right of stairway)

Rectory Renovation: Before and After Photos

Laundry Area to Left

Area to right is the new archives room)

Area opposite the new archive room

Rectory Renovation: Before and After Photos

Blue tape on floor indicates location of partition walls and door to be built in basement

Left side: Wall will screen off laundry/furnace/hot water tank area

Right Side: Wall will screen off area for archives storage. Tape on floor indicates location of

Partition Wall Built separating Laundry and Archives Room

Rectory Renovation: Before and After Photos

New Meeting Room in area opposite the Laundry and Archive Rooms

Updated and new light fixtures, wire mold along walls

Inside the Laundry Room

Rectory Renovation: Before and After Photos

View Inside New Archive Room



Archangel Michael Church donated new furnace, central air conditioner and 50 gallon hot water tank